

Inverurie Asset Condition Assessment

Final Report

04 May 2018

www.jbaconsulting.com

JBA Project Manager

Caroline Anderton BSc MSc CEnv CSci MCIWEM C.WEM
 Unit 2.1, Quantum Court
 Research Avenue South
 Heriot Watt Research Park
 Riccarton
 Edinburgh
 EH14 4AP

Revision history

Revision Ref/Date	Amendments	Issued to
P01 / 23 March 2018	Draft Report	Alistair Scotland and Lee Watson, Aberdeenshire Council
P02 / 27 April 2018	Final Report	Alistair Scotland and Lee Watson, Aberdeenshire Council
P03 / 04 May 2018	Final Report	Alistair Scotland and Lee Watson, Aberdeenshire Council
C01 / 03 April 2019	Published	Alistair Scotland and Lee Watson, Aberdeenshire Council

Contract

This report describes work commissioned by Gavin Penman, on behalf of Aberdeenshire Council, on 10 October 2017 by Purchase Order 1095192. Dougall Baillie’s representative for the contract was Scott Macphail and Aberdeenshire Council’s representative for the contract was Alistair Scotland. Christina Kampanou and Stephen Farrar of JBA Consulting carried out this work.

Prepared by Christina Kampanou BSc MEng MSc
 Assistant Engineer

Reviewed by Stephen Farrar MEng CEng MICE
 Senior Engineer

Purpose

This document has been prepared as a Final Report for Aberdeenshire Council. JBA Consulting accepts no responsibility or liability for any use that is made of this document other than by the Client for the purposes for which it was originally commissioned and prepared.

JBA Consulting has no liability regarding the use of this report except to Aberdeenshire Council.

Copyright

© Jeremy Benn Associates Limited 2018.

Carbon footprint

A printed copy of the main text in this document will result in a carbon footprint of 58g if 100% post-consumer recycled paper is used and 73g if primary-source paper is used. These figures assume the report is printed in black and white on A4 paper and in duplex.

JBA is aiming to reduce its per capita carbon emissions.

Executive summary

A structural survey was undertaken along the main watercourses of Inverurie in Aberdeenshire, the River Urie, the River Don and the old canal of the River Don.

The structural assets along the rivers were visually inspected, recorded and assessed in accordance with the Environment Agency's Condition Assessment Manual March 2012. The visual survey locates their position, identifies the risk of blockage, maintenance required and if appropriate 'quick wins'.

Properties with property level flood protection measures have been identified from an external visual survey.

The assets were generally found to be in good condition and their likely performance, assessed in this report, can be essential for effective flood risk management.

Contents

1	Introduction	1
2	River Urie	1
3	River Don	11
4	River Don Old Canal	24
5	Property Level Protection (PLP)	35

List of Figures

Contents

	iv
Figure 2-1: Plan showing the distribution of features identified in the asset condition assessment along the River Urie	2
Figure 2-2: Plan showing the distribution of features identified in the asset condition assessment along the River Urie	4
Figure 2-3: Plan showing the distribution of features identified in the asset condition assessment along the River Urie	6
Figure 2-4: Plan showing the distribution of features identified in the asset condition assessment along the River Urie	9
Figure 3-1: Plan showing the distribution of features identified in the asset condition assessment along the River Don	11
Figure 3-2: Plan showing the distribution of features identified in the asset condition assessment along the River Don	13
Figure 4-1: Plan showing the distribution of features identified in the asset condition assessment along the River Don Old Canal	24
Figure 4-2: Closer view showing the distribution of features 25-28 identified in the asset condition assessment along the River Don Old Canal	25
Figure 4-3: Plan showing the distribution of features identified in the asset condition assessment along the River Don Old Canal	30
Figure 4-4: Plan showing the distribution of features identified in the asset condition assessment along the River Don Old Canal	33
Figure 5-1: Plan showing the location of the PLP assets	35
Figure 5-2: Plan showing the properties with PLP and their house numbers	36
Figure 5-3: Possible Property Level Protection of commercial property on Works off Harlaw Drive (No. 1)	37
Figure 5-4: Property Level Protection of commercial property (Scotframe Timber Engineering Limited) off B9170 (No. 2)	38
Figure 5-5: Property Level Protection of the 17 Keithhall Road	39
Figure 5-6: Property Level Protection on 3-4 Canal Road	40

List of Tables

Table 2-1: List of structural assets shown in Figure 2-1	2
Table 2-2: List of structural assets shown in Figure 2-2	4
Table 2-3: List of structural assets shown in Figure 2-3	6
Table 2-4: List of structural assets shown in Figure 2-4	9
Table 3-1: List of structural assets shown in Figure 3-1	11
Table 3-2: List of structural assets shown in Figure 3-2	13
Table 3-3: List of structural assets shown in Figure 3-3	23
Table 4-1: List of structural assets shown in Figure 4-1 and Figure 4-2	25
Table 4-2: List of structural assets shown in Figure 4-3	31
Table 4-3: List of structural assets shown in Figure 4-4	33

Abbreviations

TBC	To be confirmed
CSO	Combined Sewer Overflow
FPS	Flood Protection Scheme
PLP	Property Level Protection
SW	Scottish Water
NRV	Non-return valve

1 Introduction

A full walkover survey was undertaken to assess the condition of structures in Inverurie in Aberdeenshire as part of the Inverurie Flood Protection Study. More specifically, the walkover was undertaken in Inverurie along the River Urie and the River Don. The asset condition assessment has been carried out in accordance with the Environment Agency's Condition Assessment Manual March 2012. Where information provided by the client indicates the risk of blockage is high, or where this is thought to be high this has been recorded. (no formal risk assessment/modelling has been carried out at this stage).

Category	Comments
Date of inspection(s)	29-30 November 2017
Inspector(s)	Stephen Farrar and Christina Kampanou
General inspection information	Weather on 29 November was wet and relatively windy. On 30 November there was snow.
Scheme information	The asset survey is on behalf of Aberdeenshire Council.
Nature of inspection(s)	The inspections were walkover surveys of the structural assets in the towns, as well as logging of any PLP within the survey lines. Photographs were taken but no topographic survey work was carried out.
Nature of assets	Culverts and bridges are the main structural assets in Inverurie. There are also embankments, retaining walls, sluice gates, outlet structures and a weir.
General condition / comments	The assets were generally found to be in good condition.

2 River Urie

Assets are listed below from upstream to downstream, with the numbering referenced in Figure 2-1, Figure 2-2, Figure 2-3 and Figure 2-4.




Figure 2-1: Plan showing the distribution of features identified in the asset condition assessment along the River Urie

Table 2-1 – List of structural assets shown in Figure 2-1

Number	Asset	Location
1	ANI1 293/077 Railway Bridge	Conglass

1- ANI1 293/077 Railway Bridge (Refer to Figure 2-1)



Upstream view of masonry bridge

Type: Single Arch Bridge
Upstream Grid Ref: NJ 75169
23324
Span (m): Unknown
Material: Masonry / Cement rendering
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Waterproofing failure - water stains.
 Slight to moderate spalling of brickwork.
 Minor mortar loss.
 Longitudinal fracture of arch soffit.
Risk of blockage: Low
Maintenance: None required
Quick Win: N/A



Upstream view of arch soffit




Figure 2-2: Plan showing the distribution of features identified in the asset condition assessment along the River Urie

Table 2-2 – List of structural assets shown in Figure 2-2

Number	Asset	Location
2	Howford Bridge B9001	B9001, Howford

2 - Howford Bridge B9001 (Refer to Figure 2-2)



Downstream face of bridge

Type: Single Arch Bridge
Upstream Grid Ref: NJ 76685 22991
Span (m): 15.43
Material: Masonry
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Some spalling of masonry.
 Minor cracks.
 Eroded banks.
 Medium scour risk (Council's Records).
Risk of blockage: Low
Maintenance: None required
Quick Win: N/A



Downstream view



Upstream view




Figure 2-3: Plan showing the distribution of features identified in the asset condition assessment along the River Urie

Table 2-3: List of structural assets shown in Figure 2-3

Number	Asset	Location
3	Park Footbridge	Birch Drive
4	Souterford Bridge	B9170 Road

3 - Park Footbridge (Refer to Figure 2-3)



Downstream face of Footbridge

Type: Private Footbridge

Upstream Grid Ref: NJ 77768
22530

Span (m): 12.65

Rise (m): 1

Material: Steel Deck/ Masonry
Abutments

Condition: Grade 1 (Very Good)

Part of FPS: No

Comments:

Fixings present.

Abutments sound.

Overgrown vegetation along banks.

Risk of Blockage: Low

Maintenance: None required

Quick Win: N/A

4 - Souterford Bridge (Refer to Figure 2-3)



Upstream face of bridge, right abutment

Type: Road Bridge

Upstream Grid Ref: NJ 77958
22168

Span (m): 19.15

Material: Steel Deck/ Masonry
Abutments

Condition: Grade 2 (Good)

Part of FPS: No

Comments:

No sign of deformation.

Seeping joints concrete abutments.

Mortar joint loss coping stones.

Risk of Blockage: Low

Maintenance: None required

Quick Win: N/A

4 - Souterford Bridge (Refer to Figure 2-3)



Upstream face of bridge, left abutment



Upstream view




Figure 2-4: Plan showing the distribution of features identified in the asset condition assessment along the River Urie

Table 2-4: List of structural assets shown in Figure 2-4

Number	Asset	Location
5	Keithhall Road Bridge	B993 (Keithhall) Road

5 – Keithhall Road Bridge (Refer to Figure 2-4)



Upstream view of bridge

Type: Arched Bridge
Upstream Grid Ref: NJ 78265 20516
Span (m): 15.5
Width (m): 5.6
Material: Masonry
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Bridge in line with watercourse.
 Some mortar joint loss of soffit.
 Slight bulge of arch soffit.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A



Upstream view of watercourse



Downstream view of watercourse

3 River Don

Assets are listed below from upstream to downstream, with numbering referenced in Figure 3-1, Figure 3-2 and Figure 3-3.




Figure 3-1: Plan showing the distribution of features identified in the asset condition assessment along the River Don

Table 3-1: List of structural assets shown in Figure 3-1

Number	Asset	Location
6	Sluice Gate and Weir	River Don Ardtannes

6 – Sluice Gate and Weir (Refer to Figure 3-1)



Sluice Gate

Type: Control Gate
Upstream grid ref: NJ 76226
19889
Material: Steel / Timber
Condition: Grade 5 (Very Poor)
Part of FPS: No
Comments:
 Mechanism not operable.
 Considerable corrosion of steel.
 Rotten timber.
 Weir upstream partially missing.
Risk of Blockage: N/A
Maintenance: N/A
Quick Win: N/A



Upstream view of sluice gate



View of Weir




Figure 3-2: Plan showing the distribution of features identified in the asset condition assessment along the River Don

Table 3-2: List of structural assets shown in Figure 3-2

Number	Asset	Location
7	SW Outfall	Inverurie Bridge footpath
8	Port Elphinstone Bridge	A96 Road
9	SW Outfall 2504	Port Elphinstone Playing Field footpath- Davidson Park
10	SW Outfall 4608	Port Elphinstone Playing Field footpath – Davidson Park
11	Davidson Park Embankment	Port Elphinstone
12	SW Outfall Check Valve NRV fitted (TBC) at MH5504	Port Elphinstone Playing Field footpath
13	Don Bridge	B996 (Elphinstone) Road
14	SW Outfall 6603	Port Elphinstone Footpath

Table 3-2: List of structural assets shown in Figure 3-2

15	Inverurie Pre Cast Ltd Flood wall	Port Elphinstone Footpath
16	Scottish Water Embankment	Port Elphinstone Footpath
17	SW CSO Outfall 8501	Port Elphinstone Footpath
18	Scottish Water Embankment	Port Elphinstone Footpath
19	Culvert outlet	Port Elphinstone Footpath
20	SW Outfall 9303	Port Elphinstone Footpath

7 – SW Outfall (Refer to Figure 3-2)



Area where the outfall should be

Type: Outfall
Upstream grid ref: NJ 77124 20399
Diameter (m): 0.3
Material: Unknown
Condition: Unknown
Part of FPS: No
Comments:
 Outfall not visible.
 Assumed to be below water level.
Risk of Blockage: Unknown
Maintenance: N/A
Quick Win: Fit NRV if source of flooding

8 - Port Elphinstone Bridge A96 (Refer to Figure 3-2)



Upstream view of bridge

Type: Continuous Steel Bridge
Upstream grid ref: NJ 77241 20490
Material: Steel Deck and Parapet/ Concrete Columns
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Over floodplain.
 Sound supports.
 No signs of cracking or deformation.
 Some water stains.
Risk of Blockage: Low
Maintenance: Keep free of debris
Quick Win: N/A

8 - Port Elphinstone Bridge A96 (Refer to Figure 3-2)



View of bridge from underneath



Upstream view of bridge

9 - SW Outfall 2504 (Refer to Figure 3-2)



View of outfall and flap valve

Type: Outfall
Upstream grid ref: NJ 77235
20552
Diameter (m): 0.675
Material: Concrete
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Fixings sound.
 Surface corrosion to mechanism.
 Not a likely cause of flooding.
Risk of Blockage: Low
Maintenance: N/A
Quick Win: N/A



View of outfall and wingwall looking downstream

10 – SW Outfall 2504 (Refer to Figure 3-2)



Area where the outfall should be

Type: Outfall
Upstream grid ref: NJ 77401
20596
Diameter (m): 0.225
Material:
Condition: Unknown
Part of FPS: No
Comments:
 Outfall not visible.
 Assumed to be below water level.
 Not a likely cause of flooding.
Risk of Blockage: Unknown
Maintenance: N/A
Quick Win: N/A

11 – Davidson Park Embankment (Refer to Figure 3-2)



View from downstream

Type: Flood Bank
Upstream grid ref: NJ 77623
20528
Width (m): 2
Material: Earth
Condition: Grade 2 (Good)
Part of FPS: Yes
 Potential to set back embankment.
Comments:
 Stable and well vegetated slope.
 Relatively steep.
 Moderately uneven crest.
 No signs of erosion.
Risk of Blockage: Low
Maintenance: Maintain
 embankment covered with
 protective vegetation.
Quick Win: N/A



View from upstream

12 – SW Outfall (Refer to Figure 3-2)



Area where outfall should be

Type: Outfall
Upstream grid ref: NJ 77561
20591
Diameter (m): 0.3
Material: Unknown
Condition: Unknown
Part of FPS: No
Comments:
 Outfall not visible.
 Assumed to be below water level.
Risk of Blockage: Unknown
Maintenance: N/A
Quick Win: Fit NRV if source of
 flooding

13 - Don Bridge (Refer to Figure 3-2)



Upstream view of Don Bridge

Type: Bridge
Upstream grid ref: NJ 77620
20620
Span (m): 53.92
Material: Reinforced Concrete
 Beam and Slab / Masonry piers
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Some concrete spalling.
 Surface damage.
 Low scour risk (Council's Record).
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A



Right Pier



View from downstream

14 – SW Outfall 6603 (Refer to Figure 3-2)



View of outfall

Type: Outfall with gate
Upstream grid ref: NJ 77659
20646
Diameter (m): Unknown
Material: Concrete
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Pipe sound.
Risk of Blockage: Low
Maintenance: N/A
Quick Win: Fit NRV if source of flooding

15 – Inverurie Pre Cast Ltd Flood Wall (Refer to Figure 3-2)



Flood Wall

Type: Private Flood Wall
Upstream grid ref: NJ 77724
20678
Thickness (m): 0.3
Height (m): From 1 to 1.7
Width (m): 1
Material: Concrete
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 No consistent foundation.
 Some spalling.
 Minor loss of joint material.
 Not likely to be waterproof.
 Unlikely to meet codified standards.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A

15 – Inverurie Pre Cast Ltd Flood Wall (Refer to Figure 3-2)



Left hand side of the wall

16 – Scottish Water Embankment (Refer to Figure 3-2)



Downstream view

Type: Embankment
Upstream grid ref: NJ 77734
20668
Material: Earth
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Informal embankment.
 Uneven crest.
Risk of Blockage: Low
Maintenance: Keep embankment
 well vegetated
Quick Win: N/A

17 – SW CSO Outfall 8501 (Refer to Figure 2-1)



Outfall

Type: Outfall
Upstream grid ref: NJ 77884
20600
Material: Concrete
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Vegetation growth at all sides of structure.
 Corrosion of pipe grill.
 Fixings still present.
 Eroded banks.
 Flood debris in surrounding area.
Risk of Blockage: High
Maintenance: Keep trash screen
 and canal free of debris

17 – SW CSO Outfall 8501 (Refer to Figure 2-1)

Quick Win: Fit a non-return valve, remove debris, remove pipe grill.



Downstream view



Upstream view

18– Scottish Water Embankment (Refer to Figure 3-2)



Upstream end

Type: Embankment
Upstream grid ref: NJ 77905 20538
Material: Earth
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Uneven crest.
 Overflown embankment.
 Relatively steep downstream.
Risk of Blockage: Low
Maintenance: Keep embankment well vegetated
Quick Win: N/A

18– Scottish Water Embankment (Refer to Figure 3-2)



Flood Debris



Downstream end

19 – Culvert outlet (Refer to Figure 3-2)



Outfall

Type: Outfall and flap valve
Upstream grid ref: NJ 77905
20378

Material: Concrete

Condition: Grade 4 (Poor)

Part of FPS: Yes

Comments:

Outfall of old Wastewater Treatment Works.

Vegetation growth between stonework.

Protective barriers partially collapsed.

Loss of mortar.

Cracks of masonry.

Slight corrosion of flap valve.

Flood debris in surrounding area.

Possibly abandoned.

Risk of Blockage: Moderate

Maintenance: Keep free of debris

Quick Win: N/A



Flap valve



Outfall side walls

20 – SW Outfall 9303 (Refer to Figure 3-2)



Outfall

Type: Outfall
Upstream grid ref: NJ 77918 20312
Material: Concrete / Brickwork
Condition: Grade 4 (Poor)
Part of FPS: No
Comments:
 Manhole exposed due to bank erosion.
 Outfall breaking up.
 Horizontal Displacement of upper part.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A




Figure 3-3: Plan showing the distribution of features identified in the asset condition assessment along the River Don

Table 3-3: List of structural assets shown in Figure 3-3

Number	Asset	Location
21	ANI1 293/068 Railway Bridge (Viaduct)	Port Elphinstone

21 – ANI1 293/068 Railway Bridge (Refer to Figure 3-3)



Upstream view of bridge

Type: Viaduct
Upstream grid ref: NJ 78087
20062
Material: Steel Deck / Masonry
 Piers
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Railway Viaduct.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A



Downstream view



Downstream view of watercourse

4 River Don Old Canal

Assets are listed below from upstream to downstream, with numbering referenced in Figure 4-1, Figure 4-2 and Figure 4-3.




Figure 4-1: Plan showing the distribution of features identified in the asset condition assessment along the River Don Old Canal




Figure 4-2: Closer view showing the distribution of features 25-28 identified in the asset condition assessment along the River Don Old Canal

Table 4-1: List of structural assets shown in Figure 4-1 and Figure 4-2

Number	Asset	Location
22	Gantry Bridge	Port Elphinstone
23	Sheet Pile Wall	Port Elphinstone
24	Gowan Bank Bridge	B993 (Elphinstone) Road
25	Embankment	Old Canal Footpath
26	Culvert	Old Canal Footpath
27	Culvert	Old Canal Footpath
28	Wall	Old Canal Footpath
29	Informal Flood Wall	Old Canal Footpath

22 – Gantry Bridge (Refer to Figure 4-1)



View of bridge

Type: Bridge
Upstream grid ref: NJ 77648
20599
Material: Steel
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 Privately owned.
Risk of Blockage: Low, although debris trapped by bridge
Maintenance: Investigate the control regime of the canal system
Quick Win: N/A

23 – Sheet Pile Wall (Refer to Figure 4-1)



Upstream view of wall

Type: Wall
Upstream grid ref: NJ 77698
20603
Material: Steel wall and concrete capping
Condition: Grade 2 (Good)
Part of FPS: No
Comments:
 No sign of movement.
 Some corrosion of piles.
 Privately owned.
Risk of Blockage: Low
Maintenance: Investigate the control regime of the canal system
Quick Win: N/A

24- Gowan Bank Bridge (Refer to Figure 4-1)



Upstream view

Type: Bridge with triple culverts
Upstream grid ref: NJ 77640
20678
Diameter of culvert (m): 0.9
Material: Concrete
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Minor cracking.
 Some spalling of concrete.
 Minor deformation of shape.
 No vegetation through culvert.
 Connects playing field flood area to canal.
Risk of Blockage: High

24- Gowan Bank Bridge (Refer to Figure 4-1)

	<p>Maintenance: Keep free of debris Quick Win: N/A</p>
--	---

25- Embankment (Refer to Figure 4-1 and Figure 4-2)



Upstream view

Type: Pedestrian Bridge / Culvert
Upstream grid ref: NJ 77790
20419

Material: Earth
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Unevenly vegetated.
 Uneven crest.
 Steep and unstable slope
 downstream.
 Scour at toe downstream.

Risk of Blockage: Already
 blocked up.

Maintenance: N/A

Quick Win: N/A



Downstream view

26 – Culvert (Refer to Figure 4-1 and Figure 4-2)



Upstream view

Type: Pedestrian Bridge / Culvert
Upstream grid ref: NJ 77814 20411
Length (m): 8 approximately
Material: Concrete
Condition: Grade 4 (Poor)
Part of FPS: No
Comments:
 Concrete spalling.
 Culvert blocked by large boulders, possibly to do with canal accident¹.
 Sediment deposition occupying the whole cross section.
Risk of Blockage: Already blocked up
Maintenance: N/A
Quick Win: N/A

27 – Culverts (Refer to Figure 4-1 and Figure 4-2)



Upstream view

Type: Culverts
Upstream grid ref: NJ 77800 20406
Material: Masonry
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Part of old Canal.
 Main flow through east canal but partially blocked.
 Eroded and overgrown banks.
 Moss & algae on stones.
 Water stains.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A

¹ Refer to <http://news.bbc.co.uk/1/hi/scotland/2731491.stm>

27 – Culverts (Refer to Figure 4-1 and Figure 4-2)



Upstream view

28 – Wall (Refer to Figure 4-1 and Figure 4-2)



Downstream view

Type: Wall
Upstream grid ref: NJ 77801
20376
Material: Concrete
Condition: Grade 2 (Good)
Part of FPS: Yes
Comments:
 Moss & algae on stones.
 Water stains.
 No sign of movement.
Risk of Blockage: Moderate
Maintenance: Keep free of debris
Quick Win: N/A



Downstream view

29 – Wall (Refer to Figure 4-1)



Upstream view

Type: Informal Flood Wall
Upstream grid ref: NJ 77860 20328
Material: Masonry
Condition: Grade 1 (Very Good)
Part of FPS: Yes
Comments: None
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A




Figure 4-3: Plan showing the distribution of features identified in the asset condition assessment along the River Don Old Canal

Table 4-2: List of structural assets shown in Figure 4-3

Number	Asset	Location
30	Footbridge	Old Canal Footpath
31	Railway Bridge	Port Elphinstone Footpath
32	Pipe Bridge	Kirkwood Commercial Park

30 – Footbridge (Refer to Figure 4-3)



Upstream view of bridge

Type: Single span footbridge
Upstream grid ref: NJ 78148
19953
Material: Concrete / Steel
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Spalling and minor cracking of abutments.
 Corrosion and deformation of handrails.
 Water stains.
Risk of Blockage: Moderate
Maintenance: Keep canal free of debris
Quick Win: N/A

31 – Railway Bridge (Refer to Figure 4-3)



Upstream view of bridge

Type: Railway Bridge over canal
Upstream grid ref: NJ 78155
19946
Material: Steel Deck / Masonry
 Abutments
Condition: Grade 3 (Fair)
Part of FPS: Yes
Comments:
 Abutments show long cracks.
 Seeping joints.
 Minor corrosion of cross girders.
 Loss of mortar.
 Spalling of brickwork.
 Timber platform below not inspected.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A

31 – Railway Bridge (Refer to Figure 4-3)



View from underneath

32 – Pipe Bridge (Refer to Figure 4-3)



View from downstream

Type: Pipe Bridge over canal
Upstream grid ref: NJ 78305
19543
Material: Steel
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Corroded parts.
Risk of Blockage: Low
Maintenance: None required
Quick Win: N/A




Figure 4-4: Plan showing the distribution of features identified in the asset condition assessment along the River Don Old Canal

Table 4-3: List of structural assets shown in Figure 4-4

Number	Asset	Location
33	Footbridge	Kirkwood Commercial Park
34	Footbridge and Weir	Kirkwood Commercial Park

33 – Footbridge (Refer to Figure 4-4)



View from downstream

Type: Footbridge
Upstream grid ref: NJ 78255
19226
Material: Steel
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Corrosion of parapet.
Risk of Blockage: Low
Maintenance: Keep canal free of
 debris
Quick Win: N/A

34 – Footbridge and Weir (Refer to Figure 4-4)



View from downstream

Type: Footbridge and weir from
 canal
Upstream grid ref: NJ 78272
19172
Material: Steel/ Masonry
Condition: Grade 3 (Fair)
Part of FPS: No
Comments:
 Slightly uneven flow over weir crest.
 Mortar loss, cracking and spalling
 of masonry wingwalls.
Risk of Blockage: Low
Maintenance: Keep canal free of
 debris
Quick Win: N/A



Downstream of weir

5 Property Level Protection (PLP)

Property Level Protection was recorded in a commercial property off B9170 (AB51 0ZH, NJ 77734 21850) and a residential property on Keithhall Road (AB51 3UA, NJ 77874 20749). A possible PLP is recorded on Works off Harlaw Drive (AB51 4SF, NJ 77230 22269) and residential properties on Canal Road (AB51 3UQ, NJ 77756 20379). Figure 5-1, Figure 5-2 and Figure 5-3 show the properties with PLP. The survey only identifies externally visible measures. Internal measures such as watertight doors, non-return valves etc. have not been identified.




Figure 5-1: Plan showing the location of the PLP assets




Figure 5-2: Plan showing the properties with PLP and their house numbers

The Property Level Protection used in the commercial properties is timber and concrete walls. Airbrick covers were used in the residential property on Keithhall Road and a possibly raised threshold in the residential properties on Canal Road. Figure 5-3, Figure 5-4, Figure 5-5 and Figure 5-6 show the PLP recorded.



Figure 5-3: Possible Property Level Protection of commercial property on Works off Harlaw Drive (No. 1)



Figure 5-4: Property Level Protection of commercial property (Scotframe Timber Engineering Limited) off B9170 (No. 2)



Figure 5-5: Property Level Protection of the 17 Keithhall Road




Figure 5-6: Property Level Protection on 3-4 Canal Road

Appendices

A Complete list of structural assets

A.1 River Urie

Table A-1 – Structural assets along the River Urie			
Number	Asset	Location	Condition
1	ANI1 293/077 Railway Bridge	Conglass	Grade 3
2	Howford Bridge B9001	Howford	Grade 2
3	Park Footbridge	Birch Drive	Grade 1
4	Souterford Bridge	B9170 Road	Grade 2
5	Keithhall Road Bridge	B993 (Keithhall) Road	Grade 2

A.2 River Don

Table A-2 – Structural assets along the River Don			
Number	Asset	Location	Condition
6	Sluice Gate and Weir	Ardtannes	Grade 5
7	SW Outfall	Inverurie Bridge footpath	
8	Port Elphinstone Bridge	A96 Road	Grade 2
9	SW Outfall 2504	Port Elphinstone Plying Field footpath	
10	SW Outfall 4608	Port Elphinstone Plying Field footpath	
11	Davidson Park Embankment	Port Elphinstone	Grade 2
12	SW Outfall (TBC) NRV fitted at MH5504	Port Elphinstone Plying Field footpath	
13	Don Bridge	B996 (Elphinstone) Road	Grade 2
14	SW Outfall	Port Elphinstone Footpath	
15	Inverurie Pre- cast Ltd. Flood wall	Port Elphinstone Footpath	Grade 2
16	Scottish Water Informal Embankment	Port Elphinstone Footpath	Grade 2
17	SW CSO Outfall 8501	Port Elphinstone Footpath	Grade 3

Table A-2 – Structural assets along the River Don

			High Risk of Blockage
18	Scottish Water Embankment	Port Elphinstone Footpath	Grade 3
19	Culvert outlet	Port Elphinstone Footpath	Grade 4
20	SW Outfall 9303	Port Elphinstone Footpath	Grade 4
21	ANI1 293/068 Railway Bridge (Viaduct)	Port Elphinstone	Grade 2

A.3 River Don Old Canal

Table A-2 – Structural assets along the River Don Old Canal

Number	Asset	Location	Condition
22	Sluice Gate	Port Elphinstone	
23	Sheet Pile Wall	Port Elphinstone	
24	Gowan Bank Bridge	B993 (Elphinstone) Road	Grade 3 High Risk of Blockage
25	Embankment	Old Canal Footpath	Grade 3 Blocked
26	Culvert	Old Canal Footpath	Grade 4 Blocked
27	Culvert	Old Canal Footpath	Grade 3
28	Wall	Old Canal Footpath	Grade 2
29	Informal Flood Wall	Old Canal Footpath	Grade 1
30	Footbridge	Old Canal Footpath	Grade 3
31	Railway Bridge	Port Elphinstone Footpath	Grade 3
32	Pipe Bridge	Kirkwood Commercial Park	Grade 3
33	Footbridge	Kirkwood Commercial Park	Grade 3
34	Footbridge and Weir	Kirkwood Commercial Park	Grade 3

JBA
consulting

Offices at

Coleshill
Doncaster
Dublin
Edinburgh
Exeter
Glasgow
Haywards Heath
Isle of Man
Limerick
Newcastle upon Tyne
Newport
Peterborough
Saltaire
Skipton
Tadcaster
Thirsk
Wallingford
Warrington

Registered Office

South Barn
Broughton Hall
SKIPTON
North Yorkshire
BD23 3AE
United Kingdom

+44(0)1756 799919
info@jbaconsulting.com
www.jbaconsulting.com
Follow us:  

Jeremy Benn Associates Limited

Registered in England 3246693

JBA Group Ltd is certified to:
ISO 9001:2015
ISO 14001:2015
OHSAS 18001:2007

